

2005 Chevrolet Cobalt L4-2.0L SC VIN P

Vehicle » Technical Service Bulletins » All Technical Service Bulletins » Ignition - Key Difficult To Remove, Binds Or Sticks

TECHNICAL

Bulletin No.: 09-02-35-005C

Date: February 07, 2011

Subject: Ignition Key Difficult to Remove, Ignition Key Binds or Sticks in Cylinder (Replace Ignition Cylinder)

Models:

2005-2009 Chevrolet Cobalt (Built Prior to April 14, 2009)

2006-2010 Chevrolet HHR (Built Prior to June 1, 2010)

2007-2009 Chevrolet Equinox (Built Prior to July 2008)

2005-2006 Pontiac Pursuit (Canada Only)

2006-2009 Pontiac Solstice (Built Prior to April 14, 2009)

2007-2009 Pontiac G5 (Built Prior to April 14, 2009), Torrent (Built Prior to July 2008)

2006-2009 Saturn SKY (Built Prior to April 24, 2009)

Supersede:

This bulletin is being revised to remove an Attention statement, update the build date for HHR and remove the CTS model. Please discard Corporate Bulletin Number 09-02-35-005B (Section 02 - Steering).

Condition

Some customers may comment that the ignition key is difficult to remove or that the key sticks or binds in the ignition cylinder.

Correction

A new ignition lock cylinder has been released to correct this concern. Replace the ignition lock cylinder following the Ignition Lock Cylinder Replacement procedure in SI. For ignition lock cylinder assembly and coding, use the instructions provided with the new cylinder.

Important

To properly seat the new ignition lock cylinder into the housing, the key must be inserted and turned to the RUN position.

Parts Information

Part Number	Description
20869121	Cylinder, Ignition Lock (Uncoded)

Warranty Information

--

Labor Operation	Description	Labor Time
E7200	Ignition Lock Cylinder Replacement	Use Published Labor Operation Time

For vehicles repaired under warranty, use the table.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT
VOLUNTARY
TECHNICIAN
CERTIFICATION

Disclaimer